
Infrared (IR) spectroscopy: fundamentals

Prof. Ivo Leito

Infrared (IR) spectral range

Near-IR (NIR) Mid-IR (IR) Far-IR Radiation: 4000 - 400 cm⁻¹ Wavenumber: 14000 - 4000 cm⁻¹ 400 - 10 cm⁻¹ Wavelength: $0.7 - 2.5 \, \mu m$ 2.5 - 25 µm 25 - 1000 µm Analysis of organic Analysis of inorganic Analysis of organic, compounds compounds inorganic and polymeric compounds Liquids, solids Mostly solids Liquids, solids, gases Mostly quantitative Qualitative (and semianalysis of well- Qualitative and quantitative analysis) known objects quantitative analysis • Semi-non-destructive Often very charcteristic Semi-non-destructive

Spectra of rabbitskin glue



Transmittance and absorbance

 At every wavenumber the signal intensity can be expressed as transmittance (%T) or absorbance (A):

$$T = \frac{I}{I_0} \cdot 100\%$$

Intensity of radiation entering a sample

 $T = \frac{I}{I_{c}} \cdot 100\%$ Intensity of radiation entering a samp Intensity transmitted (or absorbed) by the sample

$$A = log \frac{I_0}{I}$$




Lambert-Beer's Law

$$A = \varepsilon lc$$

 ε = absorptivity, I = path length, c = concentration

Vibrations


• Stretching vibrations – bond length changes




Bending (deformation) vibrations – bond angle changes

Scissoring	Twisting (out-of-plane)	Rocking	Wagging
(in-plane)		(in-plane)	(out-of-plane)

IR spectrum of linseed oil




IR spectrum of chalk (CaCO₃)



IR spectra of complex mixtures

- In the IR spectrum of the mixtures often bands overlap
- For the interpretation IR spectra of the pure compounds are needed



Summary

- It is molecular and vibrational spectroscopy
 - Bands in the IR spectrum belong to the vibrations of specific fragments in molecules
- Useful for the identification of various organic, inorganic and polymeric materials
 - Gives first general info about composition of the material
- Enables qualitative and quantitative analysis
- For the interpretation of IR spectra of complex materials reference IR spectra of pure compounds are needed.